

Instructions for Use

Surface Preparation

The surfaces to be bonded should be free of dust, oil, fat or any other dirt in order to optimise reproducible results. Lightly soiled surfaces can be cleaned with cleaner IP to create a suitable working surface.

Application

Our products are delivered ready for use. As soon as you receive them, you can dispense or use them for screen printing processes. You should store the products at 5° C for longer shelf life time.

Before using acclimate the adhesive up to room temperature. Liquid Elecolit products have to be homogenised well before application. Paste-like products can be used directly.

1-C Products have no mixing ration and pot life time.

Curing

For curing heat must be applied. The polyaddition starts at temperature over 100°C. Higher temperature will reduce the curing time. For detailed curing information, please look into the technical data sheet. Higher curing temperature will lead to better electrical conductivity and less volume resistivity.

If help is required, please contact our engineering department.
Please read the corresponding **Safety Data Sheet** for this product.